

AMENDMENT OF SOLICITATION/MODIFICATION OF CONTRACT

1. CONTRACT ID CODE PAGE OF PAGES

1 2

2. AMENDMENT/MODIFICATION NO.
00023. EFFECTIVE DATE
02/19/2010

4. REQUISITION/PURCHASE REQ. NO.

5. PROJECT NO. (If applicable)

6. ISSUED BY

DOT/FEDERAL AVIATION ADMINISTRATION
EASTERN LOGISTICS SERVICE AREA, ASO-52
1701 COLUMBIA AVENUE
COLLEGE PARK, GEORGIA 30337

7. ADMINISTERED BY (If other than Item 6)

SAME AS BLOCK 7

8. NAME AND ADDRESS OF CONTRACTOR (No., street, county, State and ZIP Code)



9A. AMENDMENT OF SOLICITATION NO.

DTFASO-09-R-00141

9B. DATED (SEE ITEM 11)

01/28/2010

TO ALL PROSPECTIVE BIDDERS



10A. MODIFICATION OF CONTRACT/ORDER NO.

*TO BE COMPLETED BY VENDOR IF NOT COMPLETE
CODE

FACILITY CODE

10B. DATED (SEE ITEM 13)

11. THIS ITEM ONLY APPLIES TO AMENDMENTS OF SOLICITATIONS

The above numbered solicitation is amended as set forth in Item 14. The hour and date specified for receipt of Offer is extended **X** is not extended.

Offers must acknowledge receipt of this amendment prior to the hour and date specified in the solicitation on as amended, by one of the following methods:

(a) By completing Item 8 and 15, and returning **1** copies of the amendment; (b) acknowledging receipt of this amendment on each copy of the offer submitted; or (c) By separate letter or telegram which includes a reference to the solicitation and amendment numbers. FAILURE OF YOUR ACKNOWLEDGMENT TO BE RECEIVED AT THE PLACE DESIGNATED FOR RECEIPT OF OFFERS PRIOR TO THE HOUR AND DATE SPECIFIED MAY RESULT IN REJECTION OF YOUR OFFER. If by virtue of this amendment you desire to change an offer already submitted, such change may be made by telegram or letter, provided each telegram or letter makes reference to the solicitation and this amendment, and is received prior to the opening hours and date specified.

12. ACCOUNTING AND APPROPRIATION DATA (If required)

13. THIS ITEM APPLIES ONLY TO MODIFICATIONS OF CONTRACTS/ORDERS, IT MODIFIES THE CONTRACT/ORDER NO.
AS DESCRIBED IN ITEM 14.

A. THIS CHANGE ORDER IS ISSUED PURSUANT TO: (Specify authority) THE CHANGES SET FORTH IN ITEM 14 ARE MADE IN THE CONTRACT/ORDER NO. IN ITEM 10A.



B. THE ABOVE NUMBERED CONTRACT/ORDER IS MODIFIED TO REFLECT THE ADMINISTRATIVE CHANGES (such as changes in paying office, appropriation data, etc.) SET FORTH IN ITEM 14.



C. THIS SUPPLEMENTAL AGREEMENT IS ENTERED INTO PURSUANT TO AUTHORITY OF:



D. OTHER (Specify type of modification and authority)

E. IMPORTANT: Contractor ☐ is not, **X** is required to sign this document and return **1** copies to the issuing office.

14. DESCRIPTION OF AMENDMENT/MODIFICATION (Organized by UCF section headings, including solicitation/contract subject matter where feasible.)

Solicitation No. DTFASO-09-R-00141, Replacement of E/G Intercooler Valves, Backflow Preventer & Fan Coil Unit Project, Miami Air Route Traffic Control Center (ARTCC), Miami, Florida

1. Page 4 - Part I - Section C - Scope of Work - Replace Page 4 with the attached revised Page 4.

2. Specification - Section 01010-1.1.A.1, Sheet No. ZMA-D-807608-C02, Details 1/CO2, 3/CO2 and 4/CO2. Delete the following Scope of Work "Replacement of 60 feet of expansion joint cover assembly, including one year warranty against leaks".

Except as provided herein, all terms and conditions of the document referenced in Item 9A or 10A, as heretofore changed, remains unchanged and in full force and effect.

15A. NAME AND TITLE OF SIGNER (Type or print)

16A. NAME AND TITLE OF CONTRACTING OFFICER (Type or print)

TRACIE B. HARRIS

15B. CONTRACTOR/OFFEROR

15C. DATE SIGNED

16B. UNITED STATES OF AMERICA

16C. DATE SIGNED

(Signature of person authorized to sign)

BY

(Signature of Contracting Officer)

3. Questions and Answers:

Question: Print ZMA-D-807608-M14 and NOTE 1 - Only to remove the butterfly valves, do we need to remove the expansion joint?

Answer: No.

Question: Scope of Work tells me to provide two (2) safety bollards to protect backflow. Prints show three (3) safety bollards. Please clarify how many bollards?

Answer: Provide 3.

Question: Drain on floor clarify the distances?

Answer: Less than 40'. Field verify.

Question: Print ZMA-D-807608-C02, tells me to replace seal and flashing but not the louver, is this correct?

Answer: Yes.

There are no further changes for this Amendment No. 0002.

PART I - SECTION C
SCOPE OF WORK

Ensure Integrity of Power Service Building envelope for Water Tightness

1. Furnish and replace the outside air intake louver sealant for the Air Handler Unit located on the second floor of the Power Service Building. Seal interface of louver and building for water tightness.
2. Furnish and replace: frame and exterior door, door hardware, door closer, panic hardware, and threshold located on the west side of the Power Service Building. Door and frame are hollow metal. Door has an access control system by Johnson Controls. Johnson Controls needs to re-program the access control system to include the new door.

Replace E/G Intercooler Valves

1. Remove and replace existing 3" intercooler isolation valves with new.
2. Remove and replace existing 6" valves in condensing water main that feeds intercooler valves as needed if these valves fail to isolate system for replacement of intercooler valves. Provide pipe hot tapping for this.

Replace Facility Backflow Preventer

1. Furnish and install 4" Backflow Preventer, valves, piping and couplings for the city main domestic water supply water to the facility. Cap existing 2" pressure reducing valve at the discharge of piping. Provide two (2) safety bollards to protect backflow preventer.
2. Furnish and install 1" Backflow Preventer, valves, piping and fittings for domestic water feed connection to the Power Service Building antifreeze tanks. Provide 1" floor drain line and connect to the closest floor drain.
3. Furnish and install 3/4" Backflow Preventer, valves, piping and fittings for domestic water feed connection to DSR Attic. Provide 1" floor drain line and connect to the closest floor drain.

Replace PBS Fan Coil Unit

1. Furnish and install (in kind) 2 ton, Fan Coil unit (FC-3), valves, piping, thermostat and wiring for the unsupported building service electric vault. Provide new insulation for piping and drain line. Test and balance fan coil unit after installation. Reuse existing branch circuit. Existing FC-3 is fed from panel BC. Coordinate with ESU and RE for CB number prior to turn off FC-3.